


HANDLING & STORAGE

HANDLING OF MATERIALS


When Glass Reinforced Polyester sheeting is handled or loaded onto a roof, a spreader bar with fabric slings should be used for large quantities. If small quantities of sheets are required they should be handled individually being careful not to bend or distort the sheet.

Handling large quantities



STACKING

Bundles should be stored well clear of the ground in an area protected from direct sunlight and moisture as well as being well ventilated. Bundles should be strapped and protected from movement by the wind.



Storage Note: Bundles that become wet should be separated and each sheet wiped dry before storage in a manner to promote the drying process. Alsynite Ultra - Cool and Evercool, require special care to avoid damaging the heat reflective surface of the sheet.